

Inter Office Memo



Coin Operated Games Division

To: Nancy Perkins
Bernie Perry Sandy Judd

From: Mike Laschinger *ML Laschinger*

Subject: DEVIATION 14180 Date: 7/26/83

On 7/7/83 a Deviation Number 14180 was issued (attached) to remove a 4.7 uf capacitor from location C-94 of the Star Wars mainboard. This deviation was issued because of the high failure rate of the NOVRAM. The results of this deviation are now a near zero reject rate. This deviation was implemented on Revision B boards.

ECN Number 11149 made schematic changes to the mainboard and is correcting the problem of the NOVRAM failing. The 4.7 uf capacitor at location C-94 was intentionally left on the parts list and is to be used on the board for Revision C. Deviation Number 14180 does not apply to Revision C of the main Star Wars board.

Per Jed Margolin, this schematic change is to correct the failing NOVRAM problem. If it does not correct the problem, I will issue another deviation to remove the capacitor again. If you have any questions regarding this matter please refer them to Jed Margolin or to me.

ML:tw

cc: R. Burkhardt
C. Mangat
J. Vaughn
R. Rekart
M. Ihrman
D. Finney
W. Woodworth
J. Margolin
M. Hally