SERVICE TIPS

EXCEPT ILLINOIS: 312-981-1000 Ext. 215 **TELEX: 253290**



X MANDATORY ON FAILURE ONLY FOR YOUR INFORMATION

ATTN:

SERVICE MANAGERS

GAME:

CHANGE LANES

SUBJECT:

+5 VOLTS RELIABILITY

SOULUTION:

ADJUST BR1'S HEAT SINK

PARTS NEEDED: NONE

PROCEDURE:

ROTATE THE HEAT SINKS ON THE BRIDGE RECTIFIERS SO THE FINS ARE PERPENDICULAR (90 DEGREE ANGLE) TO THE BOTTOM OF THE GAME. ADJUST THE +5 VOLTS SO THERE IS +5 VOLTS ON THE BOARD SET ITSELF.

TAITO AMERICA CORPORATION 1256 Estes Ave., Elk Grove Village, IL 60007

POWER SUPPLY FIGURE 1

