

10601 W. Belmont Avenue Franklin Park, Illinois 60131 Telephone (312) 451-9200



November 17, 1983

## SERVICE BULLETIN

GAME:

ASTRON BELT

SUBJECT: HITACHI AND PIONEER LASER DISC PLAYER

- Due to a shortage of Hitachi VIP 9500 Laser Disc 1. Players, the Astron Belt games will also use the Pioneer LD-V-1000 and LD-V-1001 Disc Players.
- The Hitachi and Pioneer Laser Disc Players will 2. not be interchangeable. (Game logic & video cable are different)
- When ordering a game logic board, specify if it's 3. for a Hitachi or Pioneer Disc Player with the following part number.

Hitachi Logic Board Q834-05194-0200 Pioneer Logic Board 0834-05194-0600

Andy Ducay Technical Service Manager