



SUB C
 INC L
 LD (HL)
 INC
 LD (HL)
 ADD A, C
 INC L
 LD (HL)
 INC L
 ADD IX, DE

A = FE

(4061) = F4

(4062) = F4
 A = F8

(4063) = F8
 HL = 4064
 IX = 4620

BACK B = 3

IF (IX) Z

IX CONTROL BYTES =

4600	4060
LD	4061
	4062
	4063
4620	4064
	4065
	4066
	4067
4640	4068
	4069 4069
4078	406A
40	406B

IF NZ

ADDRESS PLUS

406C	4070	4074
406D	4071	4075
406E	4072	4076
406F	4073	4077
(4600)	(4620)	(4640)
4078	407C	4080
4079	407D	4081
407A	407E	4082
407B	407F	4083